

**Ref.No: 90 /CFO/KZK/SCHOOL-ADV/2020.**

**Dated: 19/02/2020**

To,  
The President/Principal  
**Vicat D.A.V Vidya Mandir ,**  
**Chtrasala Chincholi tq,**  
**Kalaburagi Dist.**  
**Karnataka 585320**

Sir,

**Sub: Issue of "Fire Safety recommendation" to Vicat D.A.V Vidya Mandir ,**  
**Chtrasala Chincholi tq, Kalaburagi Dist. Karnataka 585320.**

**Ref : C.NO 11 /RFO/KRK/2020 Date 18/02/2020**

\*\*\*\*\*<><><><><>\*\*\*

With reference to the subject above cited, the premises of **Vicat D.A.V Vidya Mandir , Chtrasala Chincholi tq, Kalaburagi Dist. Karnataka 585320.** was inspected by Regional fire officer KALABURAGI on 18/02/2020 with respect to fire prevention, fire fighting and evacuation measures to be Provided in the above premises and Submitted building details as under.

**Details of the building / premises :-**

01	Name and Address of the Applicant.	:	The President/Principal <b>Vicat D.A.V Vidya Mandir ,</b> <b>Chtrasala Chincholi tq, Kalaburagi Dist.</b> <b>Karnataka 585320</b>
02	Name and Address of the premises.	:	<b>Vicat D.A.V Vidya Mandir ,</b> <b>Chtrasala Chincholi tq, Kalaburagi Dist.</b> <b>Karnataka 585320</b>
03	Name and address of the Building owner	:	The President/Principal <b>Vicat D.A.V Vidya Mandir ,</b> <b>Chtrasala Chincholi tq, Kalaburagi Dist.</b> <b>Karnataka 585320</b>
04	Number of buildings	:	01 No's of Building.
05	Number of floors	:	Ground floor only
06	<b><u>Floor-wise details of occupancy:-</u></b>		
	Ground floor	:	Science lab, computer lab, library , class rooms, staff room , principal room , conference room , Admin room .
07	Height of the building	:	04.25 mtrs mtrs
08	Site area	:	02 Acres



09	Built-up area of each floor:-		
	Ground floor		3711.0 sqm
10	Total built-up area	:	Total 3711.0 sqm
11	Surrounding properties:-		
	East (Front)	:	Kalaburagi Cement Plant
	West (Back)	:	Open Sapce & Private Land
	North (Side)	:	Chatrasal to Kaenako Road
	South (Side)	:	09 mtrs open Space & colony
12	<u>Set-back area available around the building :-</u>		
	East (Front)	:	06.00 mtrs
	West (Back)	:	06.00 mtrs
	North (Side)	:	06.00 mtrs
	South (Side)	:	06.00 mtrs
			The set back all around the building to be maintained as per zonal regulations

B. On inspection of this Institutional premises, the following fire prevention, fire fighting and evacuation measures recommended are considered absolutely essential from fire safety point of view :-


Sl. No. (1)	Details (02)	Existing (03)	Recommendations (04)																					
01.	Accessibility to the premises	The premises is accessible from 09.0 mtrs Chatrasal to Kaenako Road towards Northern side	Adequate																					
02	No of entrances	01 Nos entrance of width 09 mtrs	Adequate																					
03	No. of staircases available	<table border="1"> <tr> <td>Nos. of staircases</td> <td>:</td> <td>04No</td> </tr> <tr> <td>Width of staircases</td> <td>:</td> <td>1.40 Mtr.</td> </tr> <tr> <td>Width of treads</td> <td>:</td> <td>0.30 Mtrs</td> </tr> <tr> <td>Height of risers</td> <td>:</td> <td>0.15 Mtrs</td> </tr> <tr> <td>Nos. of riser per flight</td> <td>:</td> <td>12 risers provided in a flight</td> </tr> <tr> <td>Height of handrails</td> <td>:</td> <td>01.00 Mtrs.</td> </tr> <tr> <td>Head room clearance</td> <td>:</td> <td>02.50 Mtrs.</td> </tr> </table>	Nos. of staircases	:	04No	Width of staircases	:	1.40 Mtr.	Width of treads	:	0.30 Mtrs	Height of risers	:	0.15 Mtrs	Nos. of riser per flight	:	12 risers provided in a flight	Height of handrails	:	01.00 Mtrs.	Head room clearance	:	02.50 Mtrs.	Adequate
Nos. of staircases	:	04No																						
Width of staircases	:	1.40 Mtr.																						
Width of treads	:	0.30 Mtrs																						
Height of risers	:	0.15 Mtrs																						
Nos. of riser per flight	:	12 risers provided in a flight																						
Height of handrails	:	01.00 Mtrs.																						
Head room clearance	:	02.50 Mtrs.																						



04	Fire extinguisher	Provided 06 kgs of 04 No ABC fire extinguishers. 04 kgs of 08 No ABC fire extinguishers. 4.5 kgs of 04 No CO2 fire extinguishers. 01 water co2 50ltrs capacity 2 no of tested rubber glouse near by the main panel bord. 06 nos sand bucket with stand .	Adequate
05	Public address system	Not providede	---
06	safe assembly area	Not providede	---
07	First aid	Not providede	Recommended to provided First aid kit at each flore near the staircase
08	Hose reel hose.	Not providede	--
09	Water storage tank	02 NOs of 10000 ltrs Over head tank Provided	
10	At terrace tank level with minimum pressure of 3.5 kg/cm2	Not provided	---
10	Fire order	Not providede	Recommended to provide Notice boards indicating with Details of action to be taken by the employees in case of an Emergency/fire has been displayed with telephone Number of chincholli Fire Station i.e. 08475-273001 & 101 and of near by Ambulance Service
11	Fire fighting training		<b>Recommended to</b> 40% of the employees should be got trained in the prevention & fire fighting at the R.A.Mundkur Fire &Emergency Services Academy, Bannerughatta Road, Bangalore . Within 6 month of date of issue this recommendations

Hence This "Fire Safety recommendation" is issued to Vicat DAV Vidya Mandir Chatrasala chincholli kalaburagi Karnataka 585320 . subjected to strict adherence of the condition as laid down in this "Fire Safety recommendation" and to conduct mock drills periodically and the management must not extend the height of the building beyond 15.0 mts and **this** "Fire Safety recommendation" **is valid for a period of one year from the date of issue.**

Copy to: the Regional fire officer kalaburagi.

Yours faithfully  
  
**CHIEF FIRE OFFICER  
 KARNATAKA FIRE AND  
 EMERGENCY SERVICES  
 KALABURAGI ZONE  
 KALABURAGI-585103.**